

Master Format: 03 05 00 MARCH 2018

ULTRITE CLEANER

DESCRIPTION

ULTRITE CLEANER is a ready-to-use cleaner intended for use with ULTRITE COATING REMOVER from W. R. MEADOWS. This product is the second step of the two-step coating removal process.

USES

ULTRITE CLEANER is used to remove the residues from ULTRITE COATING REMOVER and to clean and prepare the surface for subsequent coatings and treatments.

FEATURES/BENEFITS

- Easy to use.
- User friendly; low odor.
- Low VOC content.

PACKAGING

1 Gallon (3.8 L) Units (4/Carton) 5 Gallon (18.93 L) Pails 55 Gallon (208.2 L) Drums

COVERAGE

75 - 200 ft.²/gal. (1.8 - 4.9 m²/L)

Coverage is approximate and may vary depending on how well the ULTRITE COATING REMOVER and the softened coating have been scraped off, concrete condition, climatic conditions, or equipment used for application. Always apply to a test area first to determine actual coverage rate before full-scale application.

SHELF LIFE

When stored indoors in original, unopened containers at temperatures between 40° - 90° F (4° - 32° C), optimum performance and best use is obtained within two years of date of manufacture.

SPECIFICATIONS

 Complies with all current federal, state, and local maximum allowable VOC requirements, including EPA, CARB, LADCO, OTC Phase I and II, and SCAQMD.

TECHNICAL DATA

VOC Content: <1 g/L

APPLICATION

Surface Preparation ... Scrape off as much as possible of ULTRITE COATING REMOVER and softened coating from the surface before cleaning with ULTRITE CLEANER.

Application Method ... Apply ULTRITE CLEANER with a mop, broom, or sprayer. Allow the product to stay on the surface for 3-5 minutes before agitating with a brush or a mop. Rinse thoroughly with water. Using a pressure washer where possible is recommended for more effective results. Repeat the process as necessary. Do not allow the product to dry.

Depending on how much ULTRITE COATING REMOVER and softened coating have been scraped off, two rounds of cleaning is recommended for optimum results.

PRECAUTIONS

Do not dilute. Protect painted, stained, and alkaline-sensitive surfaces from ULTRITE CLEANER. Rinse well with water. Do not freeze. Product is not intended to be used by on its own – must be used in conjunction with ULTRITE COATING REMOVER.

LEED INFORMATION

May help contribute to LEED credits:

MRc9: Construction and Demolition Waste Management

For most current data sheet, further LEED information, and SDS, visit www.wrmeadows.com.

CONTINUED ON THE REVERSE SIDE...

W. R. MEADOWS, INC.

P.O. Box 338 • HAMPSHIRE, IL 60140-0338 Phone: 847/214-2100 • Fax: 847/683-4544 1-800-342-5976

www.wrmeadows.com • info@wrmeadows.com

HAMPSHIRE, IL / CARTERSVILLE, GA / YORK, PA FORT WORTH, TX / BENICIA, CA / POMONA, CA GOODYEAR, AZ / MILTON, ON / SHERWOOD PARK, AB

PAGE 2 ... ULTRITE CLEANER #353-B ... MARCH 2018



LIMITED WARRANTY

W. R. MEADOWS, INC. warrants at the time and place we make shipment, our material will be of good quality and will conform with our published specifications in force on the date of acceptance of the order. Read complete warranty. Copy furnished upon request.

Disclaimer

The information contained herein is included for illustrative purposes only, and to the best of our knowledge, is accurate and reliable. W. R. MEADOWS, INC. cannot however under any circumstances make any guarantee of results or assume any obligation or liability in connection with the use of this information. As W. R. MEADOWS, INC. has no control

over the use to which others may put its product, it is recommended that the products be tested to determine if suitable for specific application and/or our information is valid in a particular circumstance. Responsibility remains with the architect or engineer, contractor and owner for the design, application and proper installation of each product. Specifier and user shall determine the suitability of products for specific application and assume all responsibilities in connection therewith.

© W. R. MEADOWS 2019 03/18-0M